









□□□□ □□□□ □□ □□ □□□□ □□□□ □□□□ -


Cutting Machine	XN	4	3	Acceptable
Laser Cutting Machine	MPS-3015D	1	2	Acceptable
4.5M CNC Processing Center	PRATIC	1	3	Acceptable
CNC Processing Meter	JNC	8	3	Acceptable
Shearing Machine	6X2500	2	3	Acceptable
Bending Machine	AG-1030II	4	3	Acceptable
Punching Machine	N/A	36	6	Acceptable
Coating Line	N/A	1	1.5	Acceptable
Lathing Machine	N/A	1	6	Acceptable
Grinding Machine	LITAO	4	6	Acceptable
Milling Machine	TONG ZHENG	2	6	Acceptable
Welding Machine	N/A	5	5	Acceptable
Tube Processing Machine	N/A	2	5	Acceptable









Report No:	19536352_P+T	Report Date:	09/Oct./2019	Assessed By	Wlwf Wang
CONFIDENTIAL		All Rights Reserved		Page No:	6 of 10

Grinding Machine	Milling Machine	Welding Machine
		
Tube Processing Machine	N/A	N/A
	N/A	N/A

1.5 Testing Machinery

Machine Name	Brand & Model No.	Quantity	Number of Year(s) Used	Condition
TMM	VM300	1	7	Acceptable
TMM		N/A		N/A
		N/A		N/A

1.6 Production Flow

No	Production Process	No	Production Process	No	Production Process
1	 Raw Materials	2	 Cutting	3	 Laser Cutting
4		5		6	

Report No:	19536352_P+T	Report Date:	09/Oct./2019	Assessed By	Wlwf Wang
CONFIDENTIAL		All Rights Reserved		Page No:	7 of 10