











# 

### Results Summary

(For details of individual tests, refer to the tables on the following pages.)

ID	Item/Heat No.	Dimensions/Type/Details	Finish	Overall Assessment
14117/01	SSBM316	180mm High, 50mm Square, Base Plate 316 Stainless steel	316L	COMPLIES


#### Remarks

After completion of the testing, the spigot was found to be in sound condition with no breakage, tearing or signs of fracture and no looseness of the fixings.

Colin Lorrimar Metallurgical Testing Manager













# Shenzhen Launch Co.,Ltd





www.launch-china.cn





 深圳市朗驰商贸有限公司SHENZHEN LAUNCH CO., LTD. 钥驰国际有限公司AUNCH INTERNATIONAL LIMITED. 季敏 Merlin Ji

Senior Sales Representative

**(**86) 189 6294 5180

## 深圳市南山区南山大道1092号亿利达大厦B区3栋5003

Room 5003, Building 3, Yilida Building, No. 1092 Nanshan Road, Nanshan District, Shenzhen, China postal code 518054

- **1** (86-755) 8603 7559
- **=** (86-755) 8637 2611
- ✓ sales06@launch-china.cn
- www.launch-china.com www.chinabalustrade.com